



United States Steel Corporation
Clairton Works
400 State Street
Clairton, PA 15025

RECEIVED

MAR 28 2006

March 20, 2006

Air Protection Division (3AP12)

Dr. Roger C. Westman
Department of Air Quality
Bureau of Air Pollution Control
301 Thirty-Ninth Street
Pittsburgh, PA 15201

U.S. Environmental Protection Agency
Region III
Air, Radiation & Toxics Division
1650 Arch Street
Philadelphia, PA 19103-2029
ATTN: Michael Ioff (3AT23)

Assistant Council
Department of Environmental Protection
Southwest Region
400 Waterfront Drive
Pittsburgh, PA 15222-4745
ATTN: Steve Hepler

Department of Justice
Environmental and Natural Resource Division
Environmental Enforcement Section
P.O. Box 7611
Ben Franklin Station
Washington, D.C. 20044
ATTN: David Street, Esq.

Subject: USS Reference Number: 06-0102
ACHD Reference Number: 7375
#2 Control Room
USS Clairton Works

Gentlemen:

The attached form confirms our verbal report of the subject incident. Any questions concerning this matter should be referred to Coleen M. Davis at 233-1015.

Sincerely,

Anton Lukac
Plant Manager
Clairton Works

NOTICE OF OUTAGE OF EQUIPMENT
ARTICLE XXI - SECTION 2108.1

1. **USS Reference Number:** 06-0102
ACHD Reference Number: 7375
2. **Date & Time of Breakdown:** Date: 03/17/06 Time: 0930 hours
3. **Company Name:** U.S. Steel Corporation - USS Clairton Works
4. **Specific Equipment Involved or Affected:** #2 Control Room
5. **BAPC Permit Number (if applicable):**
6. **Location:** Clairton, PA
7. **Nature and cause of breakdown:** Coke oven gas suction pressure dropped and coke oven gas was flared on all batteries when the #2 Control Room shut down due to a power failure. This prevented the desulfurization of the coke oven gas.
8. **Identification of Emissions:**
 - A. **Type(s) (CO, NOX, SO₂, Particulates, Hydrocarbons, etc.)**
Released products of combustion of Coke Oven Gas. Elevated H₂S in the downriver and under-firing gas line systems, causing increased SO₂ and VOC at point of combustion. This may also cause increased emissions from battery emission points; doors, lids, oftakes, charging, & stacks.
 - B. **Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality).** SO₂ is and VOC could be an eye, nose, and throat irritant.
 - C. **Amount of each type emitted (or likely to be emitted).**
Light to moderate
9. **Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).**
The vacuum axis and systems were brought on line.
10. **Facility back in operation -** Date: 03/17/06 Time: 2000 hours

Signature Coleen M. Davis Date 3/21/06
Coleen M. Davis
Senior Environmental Control Engineer Phone: 233-1015